



## 3. Accessoires de poupée | Zubehör für Spindelstock | Headstock's accessories

### 3.1 se montant dans la broche W25 | zum Einbau in die Spindel W25 | for fitting in the W25 spindle



0102-25002-000



0102-25276-000



0102-25001-000



0102-25005-000

**0102-25001-000** Pointe pleine 60°, W25 en acier trempé  
*Spindelstockspitze 60°, W25 gehärteter Stahl*  
60° male centre W25, hardened steel

**0102-25002-000** Pointe pleine 60°, W25 en métal dur  
*Spindelstockspitze 60°, W25 Hartmetall*  
60° male centre W25, tungsten carbide

**0102-25005-000** Pointe creuse 60°, W25 en acier trempé  
*Hohl-Spindelstockspitze 60°, W25 gehärteter Stahl*  
60° female centre W25, hardened steel

**0102-25276-000** Douille porte-fraise W25/Mo.2 avec vis de blocage  
*Fräseereinsatz W25/Mo.2 mit Spannschraube*  
Cutter bush W25/Mo.2 with lock screw