

102N-/102Mi-CF - W25

3. Accessoires de poupée | *Zubehör für Spindelstock* | Headstock's accessories

3.1 se montant dans la broche W25 | *zum Einbau in die Spindel W25* | for fitting in the W25 spindle



0102-25002-000



0102-25276-000



0102-25001-000



0102-25005-000

0102-25001-000 Pointe pleine 60°, W25 en acier trempé
Spindelstockspitze 60°, W25 gehärteter Stahl
60° male centre W25, hardened steel

0102-25002-000 Pointe pleine 60°, W25 en métal dur
Spindelstockspitze 60°, W25 Hartmetall
60° male centre W25, tungsten carbide

0102-25005-000 Pointe creuse 60°, W25 en acier trempé
Hohl-Spindelstockspitze 60°, W25 gehärteter Stahl
60° female centre W25, hardened steel

0102-25276-000 Douille porte-fraise W25/Mo.2 avec vis de blocage
Fräsereinsatz W25/Mo.2 mit Spannschraube
Cutter bush W25/Mo.2 with lock screw