


9	Décalage – centrage broche de reprise face au bloc porte-outils T21-T23		T23	0.015	0.012
			T22		0.012
			T21		0.010
Entreprise: Scemama SA			Machine: Q16380		
Technicien: R. Bader		Client: 		Date: 09.04.2024	